


***THIS AREA RESERVED  
FOR SIGN OFFS  
ON APPROVED PROOF.***

**Level 1 Support:**  
Customer Service Manager  
Keith Sipsma - Schawk  
269.660.3556  
keith.sipsma@schawk.com

**Level 2 Support:**  
Production Director  
Jim Cook - Schawk  
269.660.3557  
jim.cook@schawk.com

**Level 3 Support:**  
Graphics Manager - Kellogg  
Pat Coy - Kellogg  
269.961.2244  
pat.coy@kellogg.com

Color calibration chart showing color bars and grayscale steps. The color bars include PRO YEL, PRO MAG, PRO CYAN, PRO BLACK, PMS 200, and PMS 476. The grayscale steps are labeled 100, 95, 75, 50, 25, 5, 3, and 2.

Job#: 268641	Description: ALL-BRAN ~ COMPLETE WHEAT FLAKES			<b>OFFSET</b> IMPORTANT PRINTERS - NOTE Before printing, please ensure you have all reference materials. DO NOT alter this color separation without consent.
Task#: A01	EQUITY			
Cube/Count: 231	SAP#: K 177251 000	Date: 02/21/18	Operator: CAK	
	Die#: 231Cube30271B3	Orig Date: 03.30.11	Supplier: Graphic Pkg.	
		Desc.: RTEC		
Revision:				Date:
Revision:				Date: